

District Profile							
	21/08/2022	14/09/2022	Change				
District Area	1,572.86 Sq.Km						
Area Inundated	103.54 Sq.Km	107.99 Sq.Km	+4.45				
Area munuateu	6.58%	6.86%					
Crop Land	350,407.12 Acres						
Crop Land Inundated	23,161.19 Acres	21,355.12 Acres	-1,806.08				
Crop Land infundated	6.61%	6.09%					
Rainfall (Jul-Aug)	575 mm						
Population (as per 2017 Census)	880,515						
Affected Union Councils	28 Out of 28 23 out of 28						

UC-wise Affected Villages								
	Submerged in Water			Surrounded by Water				
Name	21/08/2022	14/09/2022	Change	21/08/2022	14/09/2022	Change		
BEGAN JARWAR	_	-	0	8	4	-4		
BUKERANI SHARIF	-	1	+1	5	5	0		
CHAMBER-1	-	-	0	11	-	-11		
CHAMBER-2	1	-	-1	11	4	-7		
DAD KHAN JARWAR	-	1	+1	12	1	-11		
DASORI	-	1	+1	10	8	-2		
DHINGANO BOZDAR	_	-	0	2	1	-1		
GHULAM SHAH LAGHA	_	-	0	2	_	-2		
HALE POTA	-	-	0	2	-	-2		
JHANDO MARI	-	3	+3	18	21	+3		
MANIK LAGHARI	-	-	0	2	_	-2		
MIRABAD	1	3	+2	23	23	0		
MISSAN	_	-	0	5	2	-3		
MOOLAN	-	-	0	1	_	-1		
ODEROLAL STATION	-	-	0	4	8	+4		
ODEROLAL VILLAGE	-	-	0	9	14	+5		
PAK-SANGHAR	-	-	0	16	6	-10		
PIYARO LUND	_	-	0	8	6	-2		
SANJAR CHANG	_	1	+1	18	8	-10		
SH.BHIRKIO	-	-	0	6	_	-6		
TANDO ALLAHYAR 2	1	1	0	2	8	+6		
TANDO ALLAHYAR 4	1	-	-1	4	_	-4		
TANDO SOOMRO	1	-	-1	10	11	+1		
Total	5	11	+6	189	130	-59		

**Disclaimer:** 30m resolution satellite image has been used for preliminary damage assessment and depicts status of flood inundation as of image acquisition date. The Union Council boundaries and names used in development of this product were obtained from Board of Revenue, Sindh.

Source: Landsat 8 Collection 2, 14 September 5: 51 GMT

