




No. PDMA(S)/Report-11/2019
GOVERNMENT OF SINDH
REHABILITATION DEPARTMENT
PROVINCIAL DISASTER MANAGEMENT AUTHORITY (SINDH)
PLOT NO. 26-C, MAIN KHAYABAN-E-JAMI
PHASE-VII, KARACHI
Phone: 021-99332003-5, Fax: 021-99332007
Karachi, dated: 15th August, 2019

See Distribution

Subject: MONSOON SITUATION REPORT-11 (15th Aug 2019, 10:00PM)

I am directed to refer to the subject noted above and to enclose herewith following reports for kind information please.

- | | |
|---|------------|
| 1. Summary of Losses and Damages (10:00pm) | Annexure-A |
| 2. Detail of de-watering pumps provided by PDMA (10:00pm) | Annexure-B |
| 3. Detail of rainfall recorded(mm)in Sindh (10:00pm) | Annexure-C |
| 4. Progress report rain/ monsoon (10:00pm) | Annexure-D |


Assistant Director (Ops) 15/8/19

DISTRIBUTION

1. The Senior Member, Board of Revenue, Sindh, Karachi.
2. The Secretary Rehabilitation Department, GoS, Karachi
3. The Commissioner(s)_____ (All).
4. HQ Engineering 5 Corps, Karachi
5. The Deputy Secretary (Staff) to Chief Minister Sindh, Karachi.
6. The Deputy Secretary (Staff) to Chief Secretary, Sindh, Karachi.
7. The Staff Officer to Chairman NDMA, Islamabad.
8. The PS to Minister Rehabilitation, Karachi.
9. Incharge Rain Emergency Cell, Chief Minister Secretariat, Karachi.



GOVERNMENT OF SINDH
REHABILITATION DEPARTMENT
PROVINCIAL DISASTER MANAGEMENT AUTHORITY

ANNEX-C, SITUATION REPORT No 11. DATED: 15.08.2019 (10:00pm)

S.No	Location	Rainfall(mm) (8am 9th Aug till 10am 15th Aug)	Rainfall(mm) (10 am 15th Aug till 10 pm 15th Aug)	Total
1	Karachi	155.1		155.1
3	Thatta	153.0	Not Reported (NR)	153.0
4	Badin	97.4	(NR)	97.4
5	Hyderabad	36.7	(NR)	36.7
6	Dadu	3.0	(NR)	3.0
7	Tando Jam	84.0	(NR)	84.0
8	MirpurKhas	84.2	(NR)	84.2
9	Chhor	14.0	(NR)	14.0
10	Mithi	28.0	(NR)	28.0
11	Nawabshah	26.0	(NR)	26.0
12	Padidan	0.0	(NR)	0.0
13	Sakrand	38.0	(NR)	38.0
14	Sukkur	0.0	(NR)	0.0
15	Rohri	2.0	(NR)	2.0
16	Larkana	0.0	(NR)	0.0
17	Moenjodro	0.0	(NR)	0.0
18	Jacobabad	0.0	(NR)	0.0

DEWATERING PUMP

S. No.	Name of Office / District	Dewatering Pumps already given	Dewatering Pumps given for Monsoon-2019	Mobile Fitted Dewatering Pumps 2019	Crane Fitted Vehicles 2019	TOTAL
1	Larkana	6	0	0	0	6
2	Sukkur	6	0	0	0	6
3	Jacobabad	9	0	0	0	9
4	Badin	5	12	0	0	17
5	T. M. Khan	6	0	0	0	6
6	Dadu	2	0	0	0	2
7	Mattari	2	3	0	0	5
8	Sujawal	2	5	0	0	7
9	Thatta	2	10	0	0	12
10	Jamshoro	0	3	0	0	3
11	Hyderabad	13	15	10	5	38
12	Mirpurkhas	0	5	0	0	5
13	Umarkot	0	4	0	0	4
14	Sanghar	0	4	0	0	4
15	KMC	4	0	4	3	8
16	DMC Central	4	0	0	0	4
17	DMC Korangi	6	0	1	1	7
18	DMC Malir	3	0	0	0	3
19	DMC West	6	4	1	1	11
20	DMC South	3	0	1	0	4
21	District Council Karachi	2	0	0	0	2
22	DC Malir	4	0	1	1	5
23	DC Central	4	0	1	1	5
24	DC East	9	4	1	1	14
25	DC South	2	0	1	1	3
26	Commissioner Karachi	0	0	8	4	8
	TOTAL :	100	69	29	18	198

ADDITIONAL RELIEF ITEMS

	Name of District	Tents	Mosquito Nets	Coolers	Charpai	Jerry Can
01	DC West	50	150	10	0	
02	DC Korangi	50	200	10	10	
03	Thatta	3000	5000			2500
04	Sujawal	1800	4000			
	TOTAL :	4900	9,350	20	10	2500



**GOVERNMENT OF SINDH
REHABILITATION DEPARTMENT
PROVINCIAL DISASTER MANAGEMENT AUTHORITY**

Annex-D

PROGRESS REPORT: RAIN / MONSOON 2019,

Dated: 15.08.2019 (10:00 pm)

S No.	Name of District	Sub-division/Taluka	Taluka/Location of inundated places	Progress in terms of dewatering	Affected Population	Persons in relief camps	Casualties			Remarks
							M	F	C	
1	South Karachi	-	Civil Line	98% Rain water cleared through dewatering pumps	Nil	Nil	05 Casualties Reported			05 persons dead due to electrocuted from 09-08-2019 to 12-08-2019
		-	Sadar		Nil	Nil				
		-	Arambagh		Nil	Nil				
		-	Garden		Nil	Nil				
		North			Nil	Nil				
		Nazimabad			Nil	Nil				
2	Central Karachi	Gulberg	Nil	-	Nil	Nil	-	-	-	-
		Liaquatabad	Nil	-	Nil	Nil	-	-	-	-
		Nazmabad	-	Nil	Nil	Nil	-	-	-	-
		New Karachi	-	Nil	Nil	Nil	-	-	-	-
		Umarkot	-	Umarkot	Rain water has been dewatered from all places	-	-	-	-	-
3	Umarkot	-	Samaro	Rain water has been dewatered from all places	-	-	-	-	-	-
		-	Kunri	Rain water has been dewatered from all places	-	-	1	-	-	-
		-	Pithoro	Rain water has been dewatered from all places	-	-	-	-	-	-
4	Tharparkar	-	-	Dewatering Pumps Functioning	-	-	-	-	-	
5	Shikarpur	-	Nil	Nil	Nil	Nil	Nil	Nil	Nil	-
6	Jacobabad	-	Nil	Nil	Nil	Nil	Nil	Nil	Nil	-
			Minicipal Committee T.M Khan Limit		Nil	Nil	-	-	-	

7	T.M Khan	T.M Khan	Village Shaikh	Dewatering process of accumulated rain water from all the urban area of distict T.M Khan has been completed as reported by respective Assistant Commissioners & Mukhtairkars	Nil	Nil	1	-	-	-	-
			Bhirkio		Nil	Nil	-	-	-	-	
			Village Raju Nizamani		Nil	Nil	-	-	-	-	
		B.S Karim	Village Pattar		Nil	Nil	-	-	-	-	
			Town B.S Karim		Nil	Nil	1	-	-	-	
			Village Jahan		Nil	Nil	-	-	-	-	
			Soomro		Nil	Nil	-	-	-	-	
			Village Suleman		Nil	Nil	-	-	-	-	
			Soomro		Nil	Nil	-	-	-	-	
			Village Raheem Bux Rind		Nil	Nil	-	-	-	-	
T.G Hyder	Dando City	Nil	Nil	-	-	-	-				
	T.G Hyder Town	Nil	Nil	-	-	-	-				
	Fazil Town	Nil	Nil	-	-	-	-				
8	Tando Allahyar		Nil	Nil	Nil	Nil	Nil	Nil	-	-	
			Nil	Nil	Nil	Nil	Nil	-	-		

Note: Rest of the districts have not reported.